

**PERFORMA FOR THE SAFETY OF SCHOOL BUILDING**

**( To be filled by the Head of school/ Institution)**

- 1 (a) Name of the school : Sethi Harkam Chaudhary Public
- (b) Level/Standard of School:- : Sr. Sec. School
- © Whether School is affiliated to C.B.S.E. or P.S.E.B. if affiliated then affiliation No. : Vill. Sangal School - Varanasi
- 2 Location : Kapurtihala Road, Jalandhar
- 3 Plot Area : 10 Acre
- 4 Plinth Area : 73484 sq. ft.
- 5 Number of Storey : 03
- 6 Year of construction of building. : 1998-2000
- 7 **If the building has been constructed under the Supervision of the Qualified Engineer, the following details may be given.**
- a) Name of the Engineer with Qualification : Engt. Kamal Kaur (AMIE, Civil)
- b) Address of the Engineer : 18, opp. Dr. Vikram Hospital, Wazirpur Road, Jalandhar
- c) Detail of structural drawings used in the construction. : Yes
- d) Name & Address of Architect with qualification. : Archit. Sanjay Ganda (B. Arch.)  
M/S Design Forum, Sect 26, 2nd floor  
Madhya Marg, Chandi garh
- 8 **Whether the building has been constructed for the purpose of**
- a) School : Yes
- b) Residential purpose and converted for use as a school. : No
- 9 **Material used for roofs**
- a) R.C.C. slabs : Yes
- b) R.S. Joists & Battens : No
- c) Wooden Joints & Battens. : No
- 10 **Material used for walls**
- a) Mud mortar : No
- b) Cement mortar : Yes
- c) Plaster i) Lime mortar : No
- ii) Cement mortar : Yes
- 11 **Flooring :-**
- a) Conglomerate : No
- b) Terrazo : Yes
- c) Brick paving : Yes (Partly)
- 12 A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows. : Detail Drawing Attached
- 13 Whether fire safety certificate obtained from concerned fire officer. : Yes
- 14 It is also certified that there is no any court case or stay is pending regarding this building in any Hon'ble Court. : There no any Court Case with school



**PART - II**

**SCHOOL BUILDING SAFETY CERTIFICATE**

**(TO BE FILLED BY THE S.D.E OF P.W.D. B&R DEPARTMENT)**

Name of the School: Seth Huxam chand S.D. Public Sr. Sec. School,  
Vill. Sengal Sahal, Kapurthala Road, Jalandhar

- 1) This office Assistant Engineer/Junior Engineer visited the above mentioned - School on 04/08/2023 and have visually inspected it for its safety and find it fit for normal use as a school building.
- 2) In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- 3) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging of roofs etc. immediately inspection of the undersigned be arranged to check the stability and the safety of the building.
- 4) This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (indicate year upto which it can be used) 2023-24 (up to 31-03-2024)

Ref. No. 143

Dated 08-08-2023

Subman  
Sub Divisional Engineer  
Constr. Sub. Divn. No. 4  
PWD B&R Br. Jalandhar Cantt.

SBI E-challan No. CPCHQJGR7

Date: 03-08-2023

Amount: 15,000/-

M. K. Singh